

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 417107

County Trembly Township Bristol Section of Township NE
Owner Nancy H. H. H. Address Hermania Pa
Location of property 2nd House No 8 SR 45 ON E side

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 37
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 40 G.P.M. Duration of test _____ hrs.
Drawdown NONE ft. Date July 23, 71
Static level-depth to water 29 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow Clay</u>	<u>0 Feet</u>	<u>4 Ft.</u>
<u>Brown Sand & Gravel</u>	<u>4</u>	<u>30</u>
<u>Light Brown Sand</u>	<u>30</u>	<u>37</u>
<u>White Sand</u>	<u>37</u>	<u>53</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Newbury Drilling
Address RD #1, Bristolville, O

Date Oct 30 1971
Signed Fred Newbury

*If additional space is needed to complete well log, use next consecutive numbered form.