

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 417108

County Trumbull Township Hustons Section of Township 5 W

Owner Donald Fisher Address RD #1, Box 176, Farmdale, O

Location of property 3rd house on w side of SR 193 S of SR 87

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 5/8 Length of casing 36

Test Rate 30 G.P.M. Duration of test hrs.

Type of screen Length of screen

Drawdown NONE ft. Date July 28, 78

Type of pump

Static level-depth to water 4.5 ft.

Capacity of pump

Quality (clear, cloudy, taste, odor) Clear

Depth of pump setting

Date of completion

Pump installed by

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Yellow clay	0 Feet	8	Ft.
Blue clay sand & gravel	8	36	
Blue shale	36	65	

W.

N.

SR 87

E.

• SR 92

S.

Drilling Firm Newbury Drilling

Date Oct 30, 1971

Address RD #1, Bristolville, O

Signed

*If additional space is needed to complete well log, use next consecutive numbered form.

20