

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 417113

County Trumbull Township Champion Section of Township NE
Owner Henry Malone Address airport Rd Newer Ohio
Location of property 4 mi E of SR 45 on E side of Barto East 202A

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 25 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST
(Specify one by circling)


Test Rate 3.0 G.P.M. Duration of test _____ hrs.
Drawdown ALL ft. Date 9-9-71
Static level-depth to water 21 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow clay</u>	<u>0 Feet</u>	<u>8 Ft.</u>
<u>Blue clay & gravel</u>	<u>8</u>	<u>25</u>
<u>Brown / shale</u>	<u>25</u>	<u>53</u>
<u>Berea sand Rock</u>	<u>53</u>	<u>63</u>
<u>returns to 48 ft at</u>		
<u>approx 156 PM</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Newbury Drilling
Address RD 1 Bristolville OH

Date Oct 30 1971
Signed Frank Newbury

*If additional space is needed to complete well log, use next consecutive numbered form.