

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 420388

County Huron Township Greenwich Section of Township South East
Owner Mr. Richard Zoll Address Plymouth East Road
Location of property Same as Well Log No. 420376

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 41
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 4 G.P.M. Duration of test 42 hrs.
Drawdown _____ ft. Date _____
Static level-depth to water 15 ft.
Quality (clear, cloudy, taste, odor) cloudy
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top Soil</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>Brown Clay</u>	<u>2</u>	<u>6</u>
<u>Gray Clay</u>	<u>6</u>	<u>19</u>
<u>Sand & Gravel</u>	<u>19</u>	<u>20</u>
<u>Gray Clay & Sand</u>	<u>20</u>	<u>35</u>
<u>Gray Clay & Gravel</u>	<u>36</u>	<u>40</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Chenoweth Drilling
Address P.O. Box 100, South Haven, Mich.

Date August 31, 1973
Signed Chenoweth

*If additional space is needed to complete well log, use next consecutive numbered form.