

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 421617

County Trumbull Township Howland Section of Township _____
Owner Wallace B. Rippen Jr Address 1842 Howland Walker Rd
Location of property Home Warner

CONSTRUCTION DETAILS

Casing diameter 5 3/4 Length of casing 91
Type of screen none Length of screen -
Type of pump 3/4 H.P. sub
Capacity of pump 10 g.p.m.
Depth of pump setting 158 ft
Date of completion Nov 1-71

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 5 G.P.M. Duration of test 1 hrs.
Drawdown dry ft. Date 10-29-71
Static level-depth to water 82' ft.
Quality (clear, cloudy, taste, odor)
Pump installed by R. N. Mills

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>5 Ft.</u>
<u>Sandstone</u>	<u>5</u>	<u>15</u>
<u>Shale</u>	<u>15</u>	<u>170</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Mills Drilling
Address 488 N. High St.
Cortland, O

Date 11-6-71
Signed R. N. Mills

*If additional space is needed to complete well log, use next consecutive numbered form.