

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 423157

County Putnam Township Pileas Section of Township _____
Owner Hannie H. H. H. H. Address Paradise, Ohio
Location of property 3 1/2 on Rd. P. North side Rd.

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing 30
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion July 8, 1972

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 40 G.P.M. Duration of test _____ hrs.
Drawdown 11 1/2 ft. Date _____
Static level-depth to water 10 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	39 Ft.
<u>Clay & Gravel</u>	<u>30</u>	<u>30</u>
<u>Limestone</u>	<u>9</u>	<u>9</u>
<u>Well</u>	<u>39</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. 1/2 mi East of Paradise E.
on Rd. P. North side Rd.
across from air field

S.

Drilling Firm Harry Vanderkinder Date July 8, 1972
Address Paradise, Ohio Signed Harry Vanderkinder

*If additional space is needed to complete well log, use next consecutive numbered form.