

WELL LOG AND DRILLING REPORT

ORIGINAL

62

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 423158

County Hancock Township Union Section of Township 27

Owner Don Van Horn Address 1111 East Ohio

Location of property 1 mi East of Union Township

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(Specify one by circling)

Casing diameter 4 1/2 Length of casing 25
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion July 17, 1972

Test Rate 900 G.P.M. Duration of test 1 hrs.
Drawdown 40 ft. Date _____
Static level-depth to water 10 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

0 Feet

13 Ft.

N.

20

25

8

18

W. 1 mi East of Union Township E.

1/2 mi South of Union Township

1/2 mi East of Union Township

1/2 mi South of Union Township

S.

Drilling Firm Hansel & Son

Date July 17, 1972

Address Union Township, Ohio

Signed Harry Van Horn

*If additional space is needed to complete well log, use next consecutive numbered form.