

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 423381

County Portage Township Brimfield Section of Township _____
Owner Ray Rasmussen Address 2523 Ardwell Ave Akron
Location of property 1221 Doralee Dr. Brimfield Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 6 Length of casing 53
Type of screen _____ Length of screen _____
Type of pump Submersible
Capacity of pump 12
Depth of pump setting 60
Date of completion 4-17-72

Test Rate 16 G.P.M. Duration of test 3 hrs.
Drawdown 20 ft. Date 2/16/72
Static level-depth to water 15 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Suburban Pump Co

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Clay

0 Feet

14 Ft.

Sand + Gravel

14

49

Shale

49

W.

N.

SL43

Doralee Dr
1/8 mile Well

E.

S.

Drilling Firm Suburban Pump Co
Address 1806 Sandy Lake Rd
Bavenna Ohio

Date 3/31/72
Signed Barugh Basinger

*If additional space is needed to complete well log, use next consecutive numbered form.

(21)