

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

262
No. 424336

Dr. J.K. - Sub

County SANDUSKY Township YORK Section of Township 19

Owner Limerick Lumber & Supply Address Clyde

Location of property Co. Rd. # 175

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 5/8 Length of casing 44

Test Rate 14 G.P.M. Duration of test 1 hrs.

Type of screen _____ Length of screen _____

Drawdown 0 ft. Date Nov. 22, 1922

Type of pump _____

Static level-depth to water 40 ft.

Capacity of pump _____

Quality (clear/cloudy, taste, odor) Good

Depth of pump setting _____

Pump installed by _____

Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Top Soil & Sand

0 Feet

16 Ft.

CLAY

16

40

Gray Lime

40

75

W.

N.

E.

S.

Drilling Firm Hubble Drilling

Date Nov. 22, 1922

Address Box 626, Flat Rock, O

Signed Merlin H. Hubble

*If additional space is needed to complete well log, use next consecutive numbered form.