

WELL LOG AND DRILLING REPORT

ORIGINAL 5.

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 424337

County OTTAWA Township DANBURY Section of Township
Owner GLEN TAYLOR Address Maple Road
Location of property 2450 METER RD 43440

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 55
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 3 ft. Date 12/1/72
Static level-depth to water 3 FT ft.
Quality (clear, cloudy, taste, odor) GOOD
Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>TOP SOIL</u>	<u>0 Feet</u>	<u>3 Ft.</u>
<u>CLAY</u>	<u>3</u>	<u>30</u>
<u>CLAY & GRAVEL</u>	<u>30</u>	<u>50</u>
<u>GRAVEL</u>	<u>52</u>	<u>55</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Huthe Drilling
Address Box 626 Flat Rock O

Date Dec 1 1972
Signed Merlin R. Huthe

*If additional space is needed to complete well log, use next consecutive numbered form.