

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

No. 424341

County SENECA Township THOMPSON Section of Township 12
Owner MERLIN RHUBBLE Address Box 626 Flat Rock O
Location of property VILLAGE OF FLAT ROCK CORP # 29

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 32
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 14 G.P.M. Duration of test 2 hrs.
Drawdown _____ ft. Date 6/8/73
Static level-depth to water 25 ft.
Quality (clear, cloudy, taste, odor) Good
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>TOP SOIL</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>CLAY</u>	<u>2</u>	<u>8</u>
<u>LIME STONE</u>	<u>8</u>	<u>185</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Hubble Drilling
Address Box 626 Flat Rock O

Date June 8 1973
Signed Merlin R. Hubble

*If additional space is needed to complete well log, use next consecutive numbered form.