

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

424637

County Wayne Township Salamanca Section of Township 16, 17
Owner Mose Shelton Address RD #2 Fredrickburg
Location of property 2 mi east of Fredrickburg

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 53.4
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate 20 G.P.M. Duration of test 1 hrs
Drawdown 9 ft. Date Apr. 1 - 75
Static level-depth to water 84 ft.
Quality (clear, cloudy, taste, odor) Cloudy
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top soil & Brown Clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>Clay & Sand</u>	<u>10</u>	<u>30</u>
<u>Blue shale</u>	<u>30</u>	<u>50</u>
<u>" "</u>	<u>50</u>	<u>80</u>
<u>Brown sand Rock</u>	<u>80</u>	<u>100</u>
<u>White Sand Rock</u>	<u>100</u>	<u>120</u>
<u>Water at</u>	<u>110 ft</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. County Road 2 E.

Well

S.

Drilling Firm Walter Donley
Address Holmesville

Date Apr. 1 - 75
Signed Walter Donley

*If additional space is needed to complete well log, use next consecutive numbered form.