

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

428707

County Palmer Township Xenia Section of Township _____
Owner James Harris Address Holly Springs O.R.
Location of property W.S. 68 4 miles N of Xenia

CONSTRUCTION DETAILS

Casing diameter 3 5/8 Length of casing 31
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Feb 18 1972

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 7 G.P.M. Duration of test 10 hrs
Drawdown 8 ft. Date 2/19/72
Static level-depth to water 3 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Mr. Harris

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>Blue clay</u>	<u>10</u>	<u>27</u>
<u>Shale</u>	<u>27</u>	<u>47</u>
<u>Water on top of shale</u>		
<u>Put lines in shale 1/2"</u>		
<u>Perforated casing at 27 ft.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm W.R. Crumley
Address Xenia, O.

Date March 6, 1972
Signed W.R. Crumley

*If additional space is needed to complete well log, use next consecutive numbered form.

(59)