

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

(23)
430681

County Medina Township Hinckley Section of Township NE
Owner Ron Batke Address 151 S. Rocky River Dr, Berea, Ohio
Location of property St Rt 303 1/2 M E of St Rt 94

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 126
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 12 G.P.M. Duration of test _____ hrs
Drawdown 90 ft. Date 8-18-72
Static level-depth to water 48 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Sandy Clay	0 Feet	115' ft.
Shale	115'	172'
Sand Stone	172'	210'
Water 198'		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm R E WERSHING
2175 HINCKLEY HILLS
Address HINCKLEY, OHIO 44233

Date 9-19-72
Signed R E Wershing

*If additional space is needed to complete well log, use next consecutive numbered form.

178