

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

432357

County Jefferson Township W. Pleasant Section of Township _____
Owner Mary Zellek Address Dillonvale, Pa.
Location of property IN VILLAGE of EMERSON 1 1/2 Miles W. of Pleasant

CONSTRUCTION DETAILS

Casing diameter 6 1/4 W. Length of casing 50'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion C.R. 4/1

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 50 G.P.M. Duration of test 1 hrs
Drawdown 3 ft. Date 8-31-1972
Static level-depth to water 47 ft.
Quality (clear, cloudy, Good taste) (odor) _____
Pump installed by OWNER

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Shale, Sandy	0 Feet	15 Ft.
Soap Stone	3'	18'
Sandy Shale	4'	22'
Soap Stone	5'	27'
Sand	3'6"	30'6"
Lime	2'	32'6"
Dark Shale	3'	35'6"
Lime Stone	2'	37'6"
Soap	2'	39'6"
COAL	3'6"	43'
Lime Stone	7'	50'
Shale, Porous, Dark	1'	51'
Sand Stone	9'	60'
Shale, Sandy	2'	62'
Sand Stone	7'	69'
Shale, Sandy	5'	74'

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Floyd H. Lamb
Address Cadiz, Ohio

Date 9-2-1972
Signed Floyd H. Lamb

*If additional space is needed to complete well log, use next consecutive numbered form.