WELL LOG AND DRILLING REPORT

ORIGINAL

(53)

432999

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

County Franklin Township Prairie Section of Township 9

Owner Mr James R. Newgass Address 7480 Rochelbaugh Rd

Location of property Reynoldsburg, O. Floyd Sub Division

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 81

Type of screen Perf Length of screen 3

Type of pump ✓

Capacity of pump 10

Depth of pump setting 70

Date of completion Nov 3 1973

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 10 G.P.M. Duration of test 2 hrs

Drawdown 5 ft. Date Nov 3 1973

Static level-depth to water 15 ft.

Quality (clear, cloudy, taste, odor) Clear

Pump installed by ✓

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	20 Ft.
Sand gravel	10	10
Sand & gravel	40	40
Coarse Sand & gravel	10	10

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Walter King Date Nov 3, 1973

Address 7318 Howard Rd Signed Tom Price

Blacklick O

*If additional space is needed to complete well log, use next consecutive numbered form.

7430 Rochelbaugh Rd

(51)