

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

435065

County Paulding Township Latty Section of Township 4
Owner Ronald Bendele Address R.R. 1 Paulding
Location of property 1 mile south of Broughton Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(Specify one by circling)Casing diameter 4 1/4 Length of casing 34

Type of screen _____ Length of screen _____

Type of pump _____

Capacity of pump _____

Depth of pump setting _____

Date of completion _____

Test Rate 10 G.P.M. Duration of test 1 hrsDrawdown 4 ft. Date 8-31-73Static level-depth to water 12 ft.Quality (clear, cloudy, taste, odor) clear

Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

clay	0 Feet	18 Ft.
Hard pan	18	27
Sand & Boulders	27	31
Shale	31	34
Gray limestone	34	35
water	35	

N. C 123

St. Rd. 613

BROUGHTON

W.

WELL

E.

S.

Drilling Firm M.E. ThompsonDate 8-31-73Address Scott OhioSigned M.E. Thompson

*If additional space is needed to complete well log, use next consecutive numbered form.