

WELL LOG AND DRILLING REPORT

ORIGINAL

50 ✓

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

435109

County Meigs Township Rutland Section of Township 1
Owner Pati Mitchell Address Rutland, Ohio R.D.
Location of property Cook's Gap, 1 1/2 mi. W. of Rt. 7, on Rt. 124

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 12'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST
(Specify one by circling)


Test Rate _____ G.P.M. Duration of test _____ hrs
Drawdown _____ ft. Date _____
Static level-depth to water _____ ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Soil</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>Red Rock</u>	<u>12</u>	<u>22</u>
<u>Gray Slate</u>	<u>22</u>	<u>30</u>
<u>Gray Sand</u>	<u>30</u>	<u>45</u>
<u>Gray Slate</u>	<u>45</u>	
<u>water at 30'-45'</u>		
<u>Gravel Packed</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Karmel De Long Date 9-30-72
Address Pomeroy, Ohio R.D. 2 Signed Karmel De Long

*If additional space is needed to complete well log, use next consecutive numbered form.