

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

435110

County Meigs Township Rutland Section of Township 9
Owner Milo Hutchison Address Rutland, Ohio
Location of property 1/4 mi. N. of Rutland on Rutland-Harrisonville Rd.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 45'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate _____ G.P.M. Duration of test _____ hrs
Drawdown _____ ft. Date _____
Static level-depth to water _____ ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Soil</u>	<u>0 Feet</u>	<u>18 Ft.</u>
<u>quick Sand</u>	<u>18</u>	<u>45</u>
<u>water 18'-45'</u>		
<u>Gravel Packed</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Karnel De Long Date 10-14-72
Address Pomeroy, Ohio R.T. 2 Signed Karnel De Long

*If additional space is needed to complete well log, use next consecutive numbered form.

A40