

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

435114

County Meigs Township Rutland Section of Township 2
Owner R. L. Miller Address Middleport, Ohio
Location of property Hypell Run Rd., 1/4 mi. N. of State Rt. 124

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 60'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate _____ G.P.M. Duration of test _____ hrs
Drawdown _____ ft. Date _____
Static level-depth to water _____ ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
#2 Soil, sand	0 Feet	18 Ft.
yellow Rock	18	24
Hardy Shale	24	30
Gray Slate	30	37
Red Rock	37	42
Gray Slate	42	54
Gray sand	54	65
Red Rock	65	
water at 24' & 54'		
Gravel Packed		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Karmel De Long
Address Pomeroy, Ohio Route 2

Date 1-23-73
Signed Karmel De Long

*If additional space is needed to complete well log, use next consecutive numbered form.