

WEI LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

435863

County Vinton Township Taylor Section of Township H-6

Owner Les Sackett Address Rt #1 Marysville, Ohio

Location of property Last House in Parrott Addition of County Rd 129

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 59'8

Type of screen — Length of screen —

Type of pump —

Capacity of pump —

Depth of pump setting —

Date of completion —

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 15 G.P.M. Duration of test 1 hrs

Drawdown None ft. Date June 28, 1972

Static level-depth to water 35 ft.

Quality (clear, cloudy, taste, odor) clear


Pump installed by —

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>sand</u>	<u>12</u>	<u>16</u>
<u>Clay</u>	<u>16</u>	<u>32</u>
<u>Sandy gravel</u>	<u>32</u>	<u>45</u>
<u>Clay</u>	<u>45</u>	<u>51</u>
<u>Sandy gravel fine</u>	<u>51</u>	<u>55</u>
<u>Limestone & gravel mixed</u>	<u>55</u>	<u>59</u>
<u>Limestone</u>	<u>59</u>	<u>82</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm —

Address Rt #1 Marysville, Ohio

Date June 28, 1972

Signed Clair Bushong

LOCATED

*If additional space is needed to complete well log, use next consecutive numbered form.

42