

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

166
4391.27

County LAKE Township CONCORD Section of Township S/L 10 E 11
Owner ANTHONY RODRIGUEZ Address 2193 CHILLIDTHE RD, MENTOR O
Location of property WEST SIDE HERMITAGE RD 1/4 ML NORTH OF PINECREST

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 29'
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion OCT 6 72

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 25 G.P.M. Duration of test 2 hrs
Drawdown TOTAL ft. Date OCT 6 72
Static level-depth to water 32 ft.
Quality (clear, cloudy, taste, odor) CLEAR NO
TASTE OR ODOR
Pump installed by —

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>TOP SOIL</u>	<u>0 Feet</u>	<u>1 Ft.</u>
<u>YELLOW CLAY</u>	<u>1</u>	<u>4</u>
<u>BROKEN BROWN SANDSTONE</u>	<u>4</u>	<u>9</u>
<u>BLUE SHALE</u>	<u>9</u>	<u>62</u>
<u>BLACK SHALE</u>	<u>62</u>	<u>74</u>
<u>BLUE SHALE</u>	<u>74</u>	<u>82</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm FREDEBAUGH WELL DRILLING CO Date OCT 7 1972
Address GRAND RIVER O Signed Herb Fredebaugh

*If additional space is needed to complete well log, use next consecutive numbered form.