

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

441336

County Butler Township Ross Section of Township 17
Owner Stanley Duke Address 710 Walter Fairfield Ohio
Location of property Hine Rd Hamlets Ohio

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing —
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion —

BAILING OR PUMPING TEST (Specify one by circling)

Test Rate — G.P.M. Duration of test — hrs
Drawdown — ft. Date —
Static level-depth to water — ft.
Quality (clear, cloudy, taste, odor) —


Pump installed by Dug

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top Soil	0 Feet	1 Ft.
Sub Soil	1	2
Clay Clay	2	9
Sand Clay	9	13
Clay	13	45
Shale	45	60
Dry well		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm HOOVER WELL DRILL
4253 SCIPPLE RD HAM- OHIO
Address —

Date June 20-73

Signed L. Mooney

*If additional space is needed to complete well log, use next consecutive numbered form.

33