

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

442213

County Fairfield Township Violet Section of Township RT 1-9528

Owner Ronald Isor Address Pickerington, Ohio

Location of property Marie Ann Pickerington Dr. of Columbus, Ohio

CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 32
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 8 G.P.M. Duration of test 1 hrs
Drawdown none ft. Date _____
Static level-depth to water 10 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>S + Gravel</u>	<u>0 Feet</u>	<u>32 Ft.</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm J. A. Hammer

Address 222 Lancaster, Ohio

Date 9-18-72

Signed Willis Stewart

*If additional space is needed to complete well log, use next consecutive numbered form.

303
LOCATED
303