

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

443688

80

County Morgan Township Bloom Section of Township 26
Owner Steven Edgell Address McCannelsville, O.
Location of property one mile east of SRT 376, on Co Rd 20

CONSTRUCTION DETAILS

Casing diameter 5" 10 Length of casing 86
Type of screen drilled Length of screen 40'
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Gravel Packed

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 40 G.P.M. Duration of test 1/2 hrs
Drawdown _____ ft. Date _____
Static level-depth to water 5.3 ft.
Quality (clear, cloudy, taste, odor) Clear
No odor good taste
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>top</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>clay</u>	<u>2</u>	<u>12</u>
<u>broken lime</u>	<u>12</u>	<u>20</u>
<u>grey shale</u>	<u>20</u>	<u>30</u>
<u>brown</u>	<u>30</u>	<u>45</u>
<u>grey shale</u>	<u>45</u>	<u>55</u>
<u>lime</u>	<u>55</u>	<u>65</u>
<u>light blue</u>	<u>65</u>	<u>85</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm V Benjamin
Address Malta, O Rt 2 43758

Date October 10, 1974
Signed Vera E. Benjamin

*If additional space is needed to complete well log, use next consecutive numbered form.