

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

443856

County FULTON Township Amboy Section of Township 12
Owner FRANK MCKAIN Address 4910 MONROE ST - Toledo, O
Location of property Route 64, 1000' N. of Sylvania-Metamora Rd

CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 114'
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 8 G.P.M. Duration of test 4 hrs
Drawdown 65' ft. Date 5/17/73
Static level-depth to water 52 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>CLAY (YELLOW)</u>	<u>0 Feet</u>	<u>18 Ft.</u>
<u>CLAY (GRAY)</u>	<u>18</u>	<u>54</u>
<u>CLAY & GRAVEL</u>	<u>54</u>	<u>114</u>
<u>GRAVEL</u>	<u>114</u>	<u>117</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm BOND DRILLING
Address Toledo Ohio

Date 5/17/73
Signed Bond

*If additional space is needed to complete well log, use next consecutive numbered form.