

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

443857

County LUCAS Township SYLVANIA Section of Township 30
Owner HARRY M^c CULLOUGH Address 2922 DAVIDSON
Location of property 2922 DAVIDSON - SYLVANIA, OHIO

CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 49'
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion 5/21/73

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 30 G.P.M. Duration of test 2 hrs
Drawdown 12 ft. Date 5/21/73
Static level-depth to water 38 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by OWNER

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>SAND</u>	<u>0 Feet</u>	<u>16 Ft.</u>
<u>CLAY</u>	<u>16</u>	<u>28</u>
<u>SHALE</u>	<u>28</u>	<u>49</u>
<u>LIMESTONE</u>	<u>49</u>	<u>55</u>
<u>SHALE</u>	<u>55</u>	<u>66</u>
<u>LIMESTONE</u>	<u>66</u>	<u>74</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm BOND DRILLING
Address TOLEDO, OHIO

Date 5/21/73
Signed Bond 370

*If additional space is needed to complete well log, use next consecutive numbered form.