WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

444246

County Warren Township Franklin Section of Township

Owner David Rose Address 4874 Shaker Rd

Location of property 2 miles N. of SR. 122 on Shaker Road

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 31 1/2

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 5 G.P.M. Duration of test 2 hrs

Drawdown ft. Date Aug 30 1976

Static level-depth to water 25 ft.

Quality (clear, cloudy, taste, odor) Clear

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Topsoil	0 Feet	10 Ft.
Shale, blue	10	40
Shale green	40	60
Water	40	

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Esters well Drilling Date Aug 30, 1976

Address Mainsburg Ohio Signed Lenford Esters

*If additional space is needed to complete well log, use next consecutive numbered form.

223