



WELL LOG AND DRILLING REPORT

NO. 30 44692

County Ottawa Township Benton Section of Township _____
Owner George Rarrig Address Graytown 0
Location of property Limestone, 0

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 5/8 Length of casing 36 Pumping rate _____ G.P.M.
Type of screen _____ Length of screen _____ Duration of test _____ hrs.
Type of pump _____ Drawdown _____ ft. Date _____
Capacity of pump _____ Developed capacity _____
Depth of pump setting _____ Static level - depth to water _____ ft.
Date of completion _____ Pump installed by _____

WELL LOG		SKETCH SHOWING LOCATION	
Formation	From	To	N.
mod.	0	26	
ls.		65	
water 50'			W. E.
			S.

Drilling Firm Chas Zesing Date 2-26-60
Address _____ Copied by RS