

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

451442

County Adams Township Brush Creek Section of Township _____
Owner Alvin E. Abernathy Address 1739 Kemper Ave. Cincinnati, Ohio
Location of property Near, Lynn, Ohio SR 125

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 67 ft
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 3 G.P.M. Duration of test 8 hrs.
Drawdown _____ ft. Date 14 JUNE 74
Static level-depth to water 24 ft to water
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>Clay</u>	<u>49 ft</u>	
<u>SLATE</u>	<u>26 ft</u>	
<u>Clay</u>	<u>8 ft</u>	
<u>LIMESTONE</u>	<u>22 ft</u>	
<u>TOTAL</u>	<u>60 ft</u>	
<u>Water at</u>	<u>24 ft</u>	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Taylor Outfit Date 14 June 74
Address 725 4th St. Portsmouth OH Signed Cecil J. Taylor

*If additional space is needed to complete well log, use next consecutive numbered form.