

WELL LOG AND DRILLING REPORT

36

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

453246

County MONROE Township JACKSON Section of Township 3
Owner MR DALLAS BOLEN Address SARDIS, O. RT 2
Location of property 2 MILES BELOW SARDIS, O. ON STATE RT 7

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 20'
Type of screen 0 Length of screen 0
Type of pump SUBMERSIBLE
Capacity of pump 600 G. ALPHEX
Depth of pump setting 120'
Date of completion AUG 21, 1978

(BAILING) OR PUMPING TEST (Specify one by circling)

Test Rate 5 G.P.M. Duration of test 1 hrs.
Drawdown 40 ft. Date AUG 25
Static level-depth to water 40 FT ft.
Quality (clear, cloudy, taste, odor) CLEAR


Pump installed by J.R. MIRACLE WELLS

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>RED CLAY</u>	<u>0 Feet</u>	<u>25 Ft.</u>
<u>SLATE & SANDSTONE</u>	<u>25</u>	<u>50</u>
<u>SANDSTONE & BLUE CLAY</u>	<u>50</u>	<u>75</u>
<u>LIMESTONE</u>	<u>75</u>	<u>100</u>
<u>FIRE CLAY</u>	<u>100</u>	<u>125</u>
<u>WATER AT 75'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm J.R. MIRACLE WELLS DR Date AUG 24, 1978
Address NEW MATAMOROS, O. Signed J.R. Miracle 20

*If additional space is needed to complete well log, use next consecutive numbered form.