

WELL LOG AND DRILLING REPORT

41 ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

453248

County WASHINGTON Township GRANDVIEW Section of Township 2.3
Owner MR JIMMY HENSEL JR Address NEW MATAMORAS, O. RT. 1.
Location of property ON STATE RT 7 TWO MILES SOUTH OF NEW MATAMORAS, O.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(Specify one by circling)

Casing diameter 4 1/8 Length of casing 63'
Type of screen 0 Length of screen 0
Type of pump SUBMERSIBLE
Capacity of pump 600 GAL PER HR.
Depth of pump setting 106'
Date of completion SEPT 10, 1979


Test Rate 50 G.P.M. Duration of test 1 hrs.
Drawdown 10' ft. Date OCT 1, 1979
Static level-depth to water 40' ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by J.R. MIRACLE WELL DR.

WELL LOG*

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>TOP SOIL</u>	<u>0 Feet</u>	<u>3 Ft.</u>
<u>SANDY LOAM</u>	<u>3</u>	<u>23</u>
<u>SAND & GRAVEL</u>	<u>23</u>	<u>63</u>
<u>BLUE LIME</u>	<u>63</u>	<u>80</u>
<u>FIRE CLAY</u>	<u>80</u>	<u>100</u>
<u>RED & BLUE CLAY</u>	<u>100</u>	<u>112</u>
<u>WATER</u>	<u>91'</u>	

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm J.R. MIRACLE WELL DR. Date OCT 4, 1979
Address NEW MATAMORAS, O Signed J.R. Miracle

*If additional space is needed to complete well log, use next consecutive numbered form.