

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

454155

County WARREN Township WAYNE Section of Township 4 of Cornus
Owner CLYDE LAMB Address 4th Floor, Waynesville, O
Location of property 3 First St. ~~Waynesville~~ Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 5 1/2 Length of casing 100'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test Rate 30 G.P.M. Duration of test 2 hrs.
Drawdown 80' ft. Date 6-25-23
Static level-depth to water 70 ft.
Quality (clear, cloudy, taste, odor) clean
Pump installed by CLYDE LAMB

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

CLAY

0 Feet

35' Ft.

SAND & GRAVEL

35-

100'

Water at 80'

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

CLARKSVILLE RD

1st Cornus road

4th Floor
Waynesville

31st St S23

Drilling Firm H. Lundy Well Drilling
Address Box 524 Waynesville, O

Date 7-4-23
Signed Harold Lundy

*If additional space is needed to complete well log, use next consecutive numbered form.

(53)