

WEI LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

~~7253384~~ (3)
459459

County Medina Township Granger Section of Township Medina
Owner Margie Smith Address Zip 44256
Location of property 3351 Granger Rd, Medina Ohio

CONSTRUCTION DETAILS

57'-10"

BAILING OR PUMPING TEST
(Specify one by circling)

Casing diameter 5 7/8" Length of casing 57-10
Type of screen K Length of screen L
Type of pump Deep Well Jet
Capacity of pump 10 G.P.M.
Depth of pump setting 60 ft
Date of completion about Nov 17-74

Test Rate 20 G.P.M. Duration of test 2 hrs.
Drawdown 48 ft. Date 11-14-74
Static level-depth to water 4.5 ft.
Quality (clear, cloudy, taste, odor) Cloudy should clear up on Pump
Pump installed by Paul R Baldum

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Yellow Clay	0 Feet	3 Ft.
Sandy Yellow Clay	3	9
Gray Shale mixed with		
Fine Gravel & Sand	9'	32'
Soft Shale Some Gravel	32'	51'
Gray Shale broken	51'	58'
Sandstone Dark Gray		
"Big Indian"	58'	71'
Stopped in the Big Indian		
as this water test good &		
a big well.		
Total Depth	71 feet	

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Well in P.T.
wholes open
to basement

3351 Granger Rd →

W.

E.

TO MEDINA GRANBER RD

S.

PAUL R. BALDWIN
1721 Columbia Road
Valley City, Ohio 44280

Drilling Firm Baldum Drilling Co Date 11-15-74

Address 1721 Columbia Rd Signed Paul R Baldum

Valley City 44280
*If additional space is needed to complete well log, use next consecutive numbered form.

LOCATED
268