WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

463159

County ASHTABULA Township Richmond Section of Township 306 E

Owner Mr John Ballentine Address Rd 2 Andover

Location of property ½ mile North of Leon Rd North on RT 7 first past 1st house on left

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 46

Type of screen — Length of screen —

Type of pump —

Capacity of pump —

Depth of pump setting —

Date of completion OCT 19 1975

BAILING OR PUMPING TEST
(Specify one by circling)

Test Rate 6 G.P.M. Duration of test 24 hrs.

Drawdown 6 ft. Date OCT 19 1975

Static level-depth to water 14 ft.

Quality (clear, cloudy, taste, odor) Clear

Pump installed by —

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay Gravel	0 Feet	6 Ft.
gravel-sand	6	43
Shale	43	59
WATER AT		44

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



Drilling Firm Stillman Well Drilling Date OCT 19 1975

Address Box 283 B Williamsfield Ohio Signed [illegible]

*If additional space is needed to complete well log, use next consecutive numbered form.

21