

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

463316

County Itasca Township Townsend Section of Township _____

Owner Mr. Frank Haas Address Collins, O

Location of property North of Collins on Hartland Center Rd

CONSTRUCTION DETAILS

(BAILING) OR (PUMPING TEST)
(Specify one by circling)

Casing diameter 5 5/8 Length of casing 44 Test Rate 5 G.P.M. Duration of test 10 hrs.
Type of screen _____ Length of screen _____ Drawdown _____ ft. Date Sept. 20, 1974
Type of pump _____ Static level-depth to water 18 ft.
Capacity of pump _____ Quality (clear, cloudy, taste, odor) Cloudy
Depth of pump setting _____ Does not want to clear up
Date of completion Sept. 20, 1974 Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

<u>Yellow Clay</u>	<u>0 Feet</u>	<u>10 Ft.</u>
<u>Blue Clay</u>	<u>10</u>	<u>28</u>
<u>Sand & gravel</u>	<u>28</u>	<u>29</u>
<u>Blue Clay</u>	<u>29</u>	<u>44</u>
<u>sand & gravel</u>	<u>44</u>	<u>46</u>
<u>Blk shale</u>	<u>46</u>	<u>52</u>

W.

N.

E.

S.

Drilling Firm _____

Date Sept. 20, 1974Address Collins, OhioSigned George A. Bates 37

*If additional space is needed to complete well log, use next consecutive numbered form.