

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

463848

County Polk Township Mill Section of Township 1

Owner Mrs. J. L. Patten Address 735 E. Washington St.

Location of property Goukharwala D. S. Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(Specify one by circling)

Casing diameter 5 Length of casing _____
Type of screen Perforated Length of screen _____
Type of pump Electric _____
Capacity of pump _____ 10
Depth of pump setting _____ 70
Date of completion June 29, 1976

Test Rate.....15 G.P.M. Duration of test.....2 hrs.
Drawdown.....10 ft. Date Aug 29 1976
Static level-depth to water.....4 ft.
Quality (clear, cloudy, taste, odor).....
.....
Pump installed by.....

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

	0 Feet	24 Ft.	0-24
Clay			
Sand Gravel	22	23	24-47
Clay Sand	15	15	47-62
Gravel	15	15	62-77
Gravel	10	10	77-87 TD.

Hand-drawn map showing a tract of land. The map is oriented with North (N.) at the top, South (S.) at the bottom, West (W.) on the left, and East (E.) on the right. A diagonal line runs from the North-Northwest to the South-Southeast, labeled "Tract of land". A small 'x' is marked on the South side of the diagonal line. To the left of the map, a list of numbers is written: 0-24, 24-47, 47-62, 62-77, and 77-87 TD.

Drilling Firm 10.27W King

Date June 29 1976

Address 11219 Haines Rd

Signed J. G. [unclear] [unclear]

*If additional space is needed to complete well log, use next consecutive numbered form.