

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

466359

County Lancaster Township Washington Section of Township _____

Owner Robert R. Reiter Address 5003 - Helena, Ohio

Location of property Helena, Ohio

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (Specify one by circling)

Casing diameter 4 1/2" Length of casing 21'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test Rate 5 G.P.M. Duration of test 2 hrs.
Drawdown 30 ft. Date _____
Static level-depth to water 26 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

3' Ft.

N.

Clay
Limestone

3'

90'

W.

E.

S.

Drilling Firm United Well Drilling

Date Oct 9 1973

Address 1112 E. Lawrence St.
Upper Lancaster, Ohio

Signed Robert R. Reiter

LOCATED

*If additional space is needed to complete well log, use next consecutive numbered form.