

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

467287

96

County Preble Township Somers Section of Township 14 15
Owner V. L. Treadway Address 1174 Somers-Grati Rd.
Location of property Same as address Camden, O.

CONSTRUCTION DETAILS

Casing diameter 6" o.d. Length of casing 70'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 40 ^{HR.} G.P.M. Duration of test 2 hrs.
Drawdown all the way ft. Date Nov. 16, 1976
Static level-depth to water 40 ft.
Quality (clear, cloudy, taste, odor) cloudy
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Topsoil</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>Sandy clay</u>	<u>2'</u>	<u>60'</u>
<u>Sand & Gravel</u> <u>& water</u>	<u>60'</u>	<u>70'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm V. L. Treadway Date Nov. 16, 1976
Address 1174 Somers-Grati Rd, Signed V. L. Treadway
Camden, Ohio 45311

*If additional space is needed to complete well log, use next consecutive numbered form.