

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
65 S. Front St., Rm. 815 Phone (614) 469-2646
Columbus, Ohio 43215

469556

County DeLaware Township Harover Section of Township 19
Owner Sohn Metyk Address McCurdy Rd
Location of property 3275

CONSTRUCTION DETAILS

Casing diameter 5' Length of casing 44
Type of screen - Length of screen -
Type of pump sub
Capacity of pump 10 gal/min
Depth of pump setting 80
Date of completion June 27-74

BAILING OR PUMPING TEST (Specify one by circling)


Test Rate 10 G.P.M. Duration of test 1/2 hrs.
Drawdown 30 ft. Date June 27-74
Static level-depth to water 45 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by Ralph E Sharts

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top soil	0 Feet	5 Ft.
Slag stone	5	44
gray shale	44	60
sand stone with water	60	65
gray shale	65	93
sand stone	93	96
water	95	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Sharts Well Drilling Date June 27-74
Address Rd 2# Londerville Signed Ralph E Sharts

*If additional space is needed to complete well log, use next consecutive numbered form.