

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Geological Survey
Fountain Square
Columbus, Ohio 43224 Phone

Phone (614) 466-5344

COUNTY Medina TOWNSHIP York SECTION OF TOWNSHIP
OR LOT NUMBER _____
OWNER John Chatham ADDRESS 4906 Columbia Rd.
LOCATION OF PROPERTY Same

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST (specify one by circling)	
Casing diameter <u>5"</u>	Length of casing <u>74'</u>		Test rate _____ gpm	Duration of test _____ hrs
Type of screen _____	Length of screen _____		Drawdown _____ ft	Date _____
Type of pump _____			Static level (depth to water) <u>35'</u>	ft _____
Capacity of pump _____			Quality (clear, cloudy, taste, odor) <u>Good</u>	
Depth of pump setting _____			Pump installed by _____	
Date of completion _____				
WELL LOG*			SKETCH SHOWING LOCATION	
Formations: sandstone, shale, limestone, gravel, clay	From	To	Locate in reference to numbered state highways, street intersections, county roads, etc.	
<u>Clay</u>	0 ft	10 ft		
clay Shale	10	70		
<u>Sandy shell</u>	70	70 88		
<u>Water at 85'</u>				

M. Hunt

19-14-76