

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Geological Survey
Fountain Square
Columbus, Ohio 43224 Phone

471872 53
466-5344

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 10 gpm Duration of test 1 hrs
 Drawdown 20 ft Date Dec 16, 1975
 Static level (depth to water) 20 ft
 Quality (clear, cloudy, taste, odor) Clear
 Pump installed by LANCASTER Well Service

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Yellow Clay	0 ft	18 ft
Blue Mud & Sand	18	32
Sand & Gravel	32	45
Gravel	45	50
Water	50	

Locate in reference to numbered
state highways, street intersections, county roads, etc.

no answer from driller for location.

960
50 T
910

WINDOP ESTATE

W. Walh
2078

DRILLING FIRM

DATE _____

ADDRESS

SIGNED

*If additional space is needed to complete well log, use next consecutive numbered form.

H185