

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Geological Survey
Fountain Square
Columbus, Ohio 43224 Phone (614) 466-5344

484158

COUNTY LOCAIN TOWNSHIP EATON SECTION OF TOWNSHIP
OR LOT NUMBER _____
OWNER EMERSON BLACKBURN ADDRESS 5817 Broad Blvd
LOCATION OF PROPERTY 1/2 mi S of Cape on Island

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6' Length of casing _____
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 6-27-75
Test rate _____ gpm Duration of test _____ hrs
Drawdown _____ ft Date _____
Static level (depth to water) _____ ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

SAND

0 ft

12 ft

BLUE CLAY

12

24

BROKEN ROCK

24

25

GRAY SHALE

25

44

BLACK SHALE

44

76

BLACK SHALE

76

96

GAS AT 95'

NO WATER

DRY HOLE PLUGGED

ZED

W

N

CAPE

E

WELL
XISLAND
RD

S

DRILLING FIRM DIEDERICH & SONS
ADDRESS N. Ridgely Ave. O

DATE 8-27-75
SIGNED S. Diederich

*If additional space is needed to complete well log, use next consecutive numbered form.

(96)