WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER NECESSARY – SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Geological Survey
Fountain Square
Columbus, Ohio 43224 Phone (614) 466-5344

488077 27

COUNTY GEAUGA TOWNSHIP BAINBRIDGE SECTION OF TOWNSHIP OR LOT NUMBER

OWNER DAVID LIPTAK ADDRESS 18346 SNYDER RD

LOCATION OF PROPERTY CORNER TAYLOR MAN NORTHON SNYDER

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 29

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 20 gpm Duration of test hrs

Drawdown 12 ft Date

Static level (depth to water) 45 ft

Quality (clear, cloudy, taste, odor)

Pump installed by

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay	0 ft	16 ft
Floater or		
LAYER of SAND ROCK	16	20
CLAY + GRAVEL	20	28
SAND ROCK	28	110
Reamed hole for casing		

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM F BAUMGARTNER DATE SEPT. 77

ADDRESS 12035 pond SIGNED F Baumgartner

BURTON O

*If additional space is needed to complete well log, use next consecutive numbered form.

TAYLOR MAY + SNYDER