

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Geological Survey
Fountain Square
Columbus, Ohio 43224 Phone (614) 466-5344

488601 (82)

COUNTY MORGAN TOWNSHIP Bloom SECTION OF TOWNSHIP 27
OR LOT NUMBER
OWNER RONALD E. Woodward ADDRESS MALTA BOX 165
LOCATION OF PROPERTY 2 miles NORTH EAST ON 275 E. BLOOM
OFF ST RT 60

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6 Length of casing 81'
Type of screen DRILLED Length of screen 35'
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion GRAVEL PACKED

Test rate 2 gpm Duration of test 2 hrs
Drawdown _____ ft Date _____
Static level (depth to water) 37 ft
Quality (clear, cloudy, taste, odor) CLEAR GOOD TASTE NO ODOR
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale, limestone, gravel, clay	From	To	Locate in reference to numbered state highways, street intersections, county roads, etc.
<u>BROKEN LIME</u>	0 ft	4 ft	
<u>YELLOW CLAY</u>	4	15	
<u>LIME</u>	15	16	
<u>GREY SHALE</u>	16	25	
<u>LIME</u>	25	30	
<u>GREY SHALE</u>	30	36	
<u>LIME</u>	36	38	
<u>GREY SHALE</u>	38	50	
<u>LIME</u>	50	55	
<u>DARK GREY SHALE</u>	55	75	
<u>LIME</u>	75	80	

DRILLING FIRM CLARK BENJAMIN DATE MAY 28 75
ADDRESS MALTA OHIO RT 2 SIGNED Clark Benjamin

*If additional space is needed to complete well log, use next consecutive numbered form.

53