

WELL LOG AND DRILLING REPORT

OK 29

ORIGINAL

98

496527

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Geological Survey
Fountain Square
Columbus, Ohio 43224 Phone (614) 466-5344

COUNTY MORGAN TOWNSHIP Bloom SECTION OF TOWNSHIP OR LOT NUMBER #25

OWNER JOHN MAUTZ ADDRESS R.R., Rokeby Lock, Ohio

LOCATION OF PROPERTY St. Rt. #60, 1 mile North of Rokeby Lock

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(Specify one by circling)

Casing diameter 5" I.D. Length of casing 32 1/2

Test rate 20 gpm Duration of test 4 hrs

Type of screen PERF. Length of screen 5'

Drawdown 21 ft Date Nov 11, 1976

Type of pump _____

Static level (depth to water) 16 ft

Capacity of pump _____

Quality (clear, cloudy, taste, odor) cloudy - No BAD

Depth of pump setting _____

TASTE OF DOOR

Date of completion _____

Pump installed by OWNER

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

SANDY LOAM	0 ft	3 ft
DRY SAND & GRAVEL	3'	27'
GRAY CLAY	27'	29'
SAND & GRAVEL	29'	32 1/2'

W

MUSKINGUM RIVER

N

WELL

St. Rt. #60

745

ROKEBY
LOCK

E

S

Hit water at 29'

DRILLING FIRM Treadway Well Drill

DATE Nov 12 1976

ADDRESS Rt #2, Stockport, O

SIGNED A. L. Treadway

*If additional space is needed to complete well log, use next consecutive numbered form.