

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

498835

COUNTY Summit TOWNSHIP Franklin SECTION OF TOWNSHIP _____
OWNER Daniel Corbin ADDRESS 7010 S. Clave, Mass. Rd
LOCATION OF PROPERTY 7203 Cleveland Massillon Rd, Clinton

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5" Length of casing 26' Test rate 40 gpm Duration of test 2 hrs
Type of screen _____ Length of screen _____ Drawdown 0 ft Date 11-6-80
Type of pump _____ Static level (depth to water) 20' ft
Capacity of pump _____ Quality (clear, cloudy, taste, odor) _____
Depth of pump setting _____ Pump installed by _____
Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION


Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>Sand + Clay</u>	<u>0 ft</u>	<u>12 ft</u>
<u>Sand + Gravel</u>	<u>12</u>	<u>19</u>
<u>Sandstone</u>	<u>19</u>	<u>38</u>



DRILLING FIRM

DATE

ADDRESS

SIGNED

Weekley Well Drilling
2656 Vandenberg Rd Oak, O

11-6-80

E. Weekley

*If additional space is needed to complete well log, use next consecutive numbered form.