

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

499520

COUNTY Cham TOWNSHIP Urbana SECTION OF TOWNSHIP East
OWNER Bill Heitman ADDRESS 393 N. Dugan Rd
LOCATION OF PROPERTY North Dugan Rd 39.3

CONSTRUCTION DETAILS

Casing diameter 6.00 Length of casing 82-3
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting 78 ft
Date of completion _____

BAILING OR PUMPING TEST (specify one by circling)

Test rate 15 gpm Duration of test 1/2 hrs
Drawdown None ft Date 12-31-77
Static level (depth to water) 62 ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft

7 ft

7

80

80


82

82

WATER 30 ft

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM

De Lang Well Drilling
2614 E. Knysna Rd

DATE

12-31-77

SIGNED

Floyd De Lang

*If additional space is needed to complete well log, use next consecutive numbered form.