

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

499844

A

COUNTY Pike TOWNSHIP Bearer SECTION OF TOWNSHIP X (24)
OWNER Carla Pasqualone ADDRESS Bearer Route 1
LOCATION OF PROPERTY 1/2 mi. East of Bearer on alt 124

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 6.00 Length of casing 86 Test rate 6 1/2 gpm Duration of test 4 hrs
Type of screen stairless Length of screen 4 ft Drawdown 2.5 ft Date 6/14/76
Type of pump jet Static level (depth to water) 50 ft
Capacity of pump 100 Quality (clear, cloudy, taste, odor) clear
Depth of pump setting _____ Pump installed by _____
Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

clay	0 ft	70 ft
sand	70	72
clay	72	74
sand	74	87
mud	87	92
water at 87		

Screen legged
5 ft

N
2.5 mi. S.W.
W. 1/2 Sec. 24
T. 24 N. R. 1 E
alt 124
S

DRILLING FIRM Calvert Shale

DATE 6/24/76

ADDRESS Jackson RFD 3

SIGNED Calvert Shale

*If additional space is needed to complete well log, use next consecutive numbered form.

21