

WELL LOG AND DRILLING REPORT

ORIGINAL

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

500392

COUNTY PORTAGE TOWNSHIP BRIMFIELD SECTION OF TOWNSHIP EAST
OWNER LARRY MILLER ADDRESS 4680 ESTES DR
LOCATION OF PROPERTY 4680 ESTES DR

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 5 Length of casing 26 Test rate 12 gpm Duration of test _____ hrs
Type of screen _____ Length of screen _____ Drawdown 5 ft Date _____
Type of pump _____ Static level (depth to water) 18 ft
Capacity of pump _____ Quality (clear, cloudy, taste, odor) CLEAR
Depth of pump setting _____ Pump installed by _____
Date of completion _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

YELLOW CLAY	0 ft	18 ft
CLAY & SAND	18	25
SANDSTONE	25	38
SHALE	38	60

W

N

HOWE Rd.

ESTES DR



E

S

DRILLING FIRM Fisher Well Drilling DATE 10-22-79
ADDRESS 199 NOTWOOD SIGNED Wm Fisher
TALLMADGE

*If additional space is needed to complete well log, use next consecutive numbered form.